

# INTERNATIONAL TRUCK AND ENGINE CORPORATION 4201 WINFIELD ROAD, WARRENVILLE, IL 40355

TRUCK GROUP

**SAFETY RECALL 04511** 

September 2004

Dear International Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. International® has decided that a defect, which relates to motor vehicle safety, exists in the **engine harness routing** of certain 9200*i*, 9400*i*, 9900*i* and 9900*i*x bullt 6/2/2002 thru 1/13/2004 with Cummins ISX engines. The vehicle identified on the enclosed card fits this description and our records show that you own this vehicle. Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

### REASON FOR THIS RECALL

The engine electrical harness can chafe against sharp edges on the engine. There are a number of different failures that could occur as many functions of the vehicle are processed through this harness.

### RISK TO MOTOR VEHICLE SAFETY

The modes of fallure that could occur that may affect highway safety are:

- Sudden acceleration without warning.
- Activation of engine compression brake without warning.
- Engine speed dropping to Idle without warning.
- Alternator overload and possible fire without warning.
- Loss of engine ECM power resulting in engine shutdown without warning.

## **ACTION YOU SHOULD TAKE**

- Our records show that you are the owner of the vehicle identified on the enclosed card. If you are not the owner, please read paragraph number 6.
- Please contact your local international dealer, with your recall card in hand, to schedule an appointment to have your vehicle repaired.
- Dealers will have parts and instructions to make the repair by 9/10/2004. The repair will be performed without charge to you and will take approximately 1 hour. Have your dealer verify and correct your address, if necessary.

- If your local international dealer performs the repair, they will submit a warranty claim; therefore, you <u>DO NOT</u> have to mail in the campaign card.
- If the vehicle will not or cannot be corrected, please mark on the enclosed card under "CHECK ONE" the box which best describes why the vehicle will not be repaired, and return the postage-prepaid card to us.
- 6. In the event you do not own the vehicle described on the card, please complete the card, fill in the new customer name and address if known, and return it to us. This information will allow us to update our records so we can contact the new owner and you will not be contacted again regarding this recall.

# REIMBURSEMENT OF REPAIRS COMPLETED PRIOR TO THE RELEASE OF THIS RECALL

If you paid to repair your vehicle for this defect prior to receiving this recall letter, you may be eligible for reimbursement of the repair costs if they were incurred between 9/01/2003 and 9/30/2004. Contact your local international dealer, with your original repair documentation and proof of payment, and the service advisor will determine what if any of the repair costs will qualify for reimbursement. International dealers determine what repair costs are eligible for reimbursement. However, if you choose not to work through an international dealer, you may submit the enclosed "REQUEST FOR REIMBURSEMENT" form, repair documentation, and proof of payment to:

International Truck and Engine Corporation
Warrenty Claim Center Reimbursement Department
P.O. Box 888
Warrenville, IL 80555

### <u>IF YOU NEED ASSISTANCE</u>

If you take your vehicle to your international dealer on a mutually agreed upon service date, and the dealer does not remedy this condition without charge on that date or within five days, you can obtain assistance by following the procedure described in the Owner Assistance Guide section in your Owner's Manual or by calling toil free 1-800-448-7825.

You may also wish to aubmit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, D.C., 20590, or call the toll-free Auto Safety Hot Line at 1-888-327-4236 if your International dealer falls to repair or is unable to remedy this condition without charge or within a reasonable time.

We request your prompt attention to the correction of this defect and apologize for any inconvenience this may cause you.

# INTERNATIONAL TRUCK AND ENGINE CORPORATION